

SUMMARY OF COOLING TOWER TESTING STATUS (Clayton)

Building No.	CT	Building	Last Sampling Date	Test	Status
5	43	Krongold Centre S. Roof Plant Room57 Scenic Bvd			System Empty
11S	51	Humanities South- 9th floor unit 1 20 Chancellors Walk			System Empty
11S	56	Humanities South- 9th floor unit 2 20 Chancellors Walk			System Empty
12	37	Law School - Roof Area 15 Ancora Imparo Way			System Empty
13D	34/35	Medical 13D South Roof 35 Rainforest Walk	6 October 2021	HCC & Leg	Clear
13F	31/32	Medical 13F Roof Plant Room 26 Innovation Walk	6 October 2021	HCC & Leg	Clear
17	29	Biology - Roof Area 18 Innovation Walk			System Empty
18	26	Zoology West - Roof Area 25 Rainforest Walk			System Empty
23	21	Chemistry - South West Roof 17 Rainforest Walk			System Empty
23	23	Chemistry East Roof Area 17 Rainforest Walk	6 October 2021	HCC & Leg	Clear
23	58	Chemistry East Roof Area 17 Rainforest Walk	6 October 2021	HCC & Leg	Clear
23	59	Chemistry East Roof Area 17 Rainforest Walk	6 October 2021	HCC & Leg	Clear
25	49/50	Eastern Science Lecture Theatres 15 Rainforest Walk			System Empty
28	10	Mathematics Building Ground North 9 Rainforest Walk	6 October 2021	HCC & Leg	Clear
30	08	Hargrave-Andrew Library Roof 13 College Walk	6 October 2021	HCC & Leg	Clear
35	57	Engineering 35 West Roof 16 Alliance Lane			System Empty
36	06	Engineering 36 West Roof 18 Alliance Lane			System Empty
37	05	Engineering 37 South East Roof 17 Alliance Lane	6 October 2021	HCC & Leg	Clear
37	01	North Ground - Engineering 37 17 Alliance Lane	6 October 2021	HCC & Leg	Clear
68	46/47	Performing Arts Centre - East Roof 55 Scenic Bvd	6 October 2021	HCC & Leg	Clear
75	52/53	STRIP 1 Building 75 Roof 15 Innovation Walk	6 October 2021	HCC & Leg	Clear
75	54	STRIP 1 Building 75 Roof 15 Innovation Walk	6 October 2021	HCC & Leg	Clear
76	60/61	STRIP 2 Building 76 Roof 19 Innovation Walk	6 October 2021	HCC & Leg	Clear
86	62/63	Green Chemical Futures 13 Rainforest Walk	6 October 2021	HCC & Leg	Clear

SUMMARY OF COOLING TOWER TESTING STATUS (Caulfield)

Building No.	Building.	Last Sampling Date	Test	Status
502	Building B Caulfield #1	4 October 2021	HCC & Leg	Clear
502	Building B Caulfield #2	4 October 2021	HCC & Leg	Clear
510	Building H Caulfield	4 October 2021	HCC & Leg	Clear
518	Building S Caulfield	4 October 2021	HCC & Leg	Clear

If the status of a cooling tower is defined as 'Not Clear' please contact John Luxford (X53042) or Alex Precht (X51515) before a Roof Access Permit is issued.